

Martin	Construction	BI0020F	East and Westbound	1409.76 Feet West of SH0137 on BI0020F	1124.64 Feet East of SH0137 on BI0020F	0.18 mile(s) before 0340	0.30 mile(s) after 0340	4/9/2024 2:31:00 PM	8/15/2024 5:00:00 PM	
Condition Descriptions			- Follow the marked detour							
Martin	Construction	SH0176	East and Westbound	1314.72 Feet West of FM3033 on SH0176	469.92 Feet West of FM3033 on SH0176	0.01 mile(s) before 0300	0.15 mile(s) after 0300	6/12/2024 3:18:00 PM	8/2/2024 5:00:00 PM	
Condition Descriptions			- Multiple lane closures.							
Martin	Closed	SH0137	North and Southbound	10.56 Feet North of BI0020F on SH0137	1341.12 Feet South of BI0020F on SH0137	0.65 mile(s) after 0320	0.91 mile(s) after 0320	4/9/2024 2:32:00 PM	8/15/2024 5:00:00 PM	
Condition Descriptions			- The roadway is closed due to construction.							
Midland	Construction	IH0020	East and Westbound	1.364 Miles West of FM1788 on IH0020	1.014 Miles West of SH0158 on IH0020	0.05 mile(s) after 0125	0.34 mile(s) after 0130	7/30/2024 8:00:00 AM	8/2/2024 5:00:00 PM	
Condition Descriptions			- Daytime closure only.							
Midland	Construction	IH0020	East and Westbound	1525.92 Feet East of BS0158B on IH0020	0.599 Miles East of SH0158 on IH0020	0.01 mile(s) before 0135	0.05 mile(s) before 0132	3/14/2024 9:26:00 AM	12/31/2024 5:00:00 PM	
Condition Descriptions			- Delays due to slow moving road repair operations.							
Midland	Construction	SH0191	North and Southbound	913.44 Feet South of SS0588 on SH0191	522.72 Feet North of SH0349 on SH0191	0.34 mile(s) after 0266	0.15 mile(s) before 0272	3/19/2024 9:30:00 AM	1/31/2025 5:00:00 PM	
Condition Descriptions			- Detour to the frontage road							
Pecos	Construction	US0067	North and Southbound	0.968 Miles South of IH0010 on US0067	26.995 Miles South of IH0010 on US0067	0.58 mile(s) before 0850	0.25 mile(s) after 0876	6/11/2024 9:22:00 AM	9/1/2024 10:00:00 AM	
Condition Descriptions			- Delays due to slow moving road repair operations.							

Pecos	Construction	US0067	North and Southbound	3.668 Miles North of IH0010 on US0067	1652.64 Feet East of IH0010 on US0067	0.53 mile(s) before 0822	0.82 mile(s) after 0824	6/11/2024 9:00:00 AM	10/31/2024 10:00:00 AM	
Condition Descriptions			- One-way traffic control signal.							
Reeves	Construction	FM1450	East and Westbound	681.12 Feet East of FM1776 on FM1450	5.603 Miles East of US0285 on FM1450	0.3 mile(s) before 0220	0.3 mile(s) before 0200	9/5/2023 5:00:00 AM	4/15/2025 6:00:00 PM	
Condition Descriptions			- Follow the marked detour							
Reeves	Construction	IH0010	East and Westbound	1.189 Miles East of IH0020 on IH0010	1209.12 Feet West of IH0020 on IH0010	0.31 mile(s) before 0188	0.06 mile(s) after 0186	8/1/2024 8:18:00 AM	8/30/2024 5:30:00 PM	
Condition Descriptions			- Alternating lanes closed.							
Reeves	Construction	US0285	North and Southbound	1932.48 Feet North of FM1216 on US0285	1.274 Miles South of FM1450 on US0285	0.09 mile(s) after 0368	0.00 mile(s) after 0374	6/12/2024 8:29:00 AM	8/15/2024 5:00:00 PM	
Condition Descriptions			- Follow the marked detour							
Reeves	Closed	BI0020B	East and Westbound	2.049 Miles East of US0285 on BI0020B	15.84 Feet East of FM0516 on BI0020B	0.31 mile(s) after 0228	0.95 mile(s) after 0232	8/2/2024 11:55:00 AM	8/2/2024 4:15:00 PM	
Condition Descriptions			- The roadway is closed due to an accident.							
Upton	Construction	RM2594	North and Southbound	491.04 Feet South of RM2401 on RM2594	0 Feet North of RM1555 on RM2594	0.05 mile(s) after 0352	0.06 mile(s) after 0367	3/13/2024 6:14:00 PM	10/1/2025 5:00:00 PM	
Condition Descriptions			- All traffic reduced to one lane, two-way traffic control in place, be							
Upton	Construction	US0385	North and Southbound	850.08 Feet North of FM0305 on US0385	8.631 Miles North of FM0305 on US0385	0.08 mile(s) after 0410	0.03 mile(s) before 0400	1/3/2024 4:34:00 PM	1/3/2025 5:00:00 PM	
Condition Descriptions			- Watch for flag personnel directing traffic.							

Ward	Construction	IH0020	Westbound	1019.04 Feet North of FM0516 on IH0020	1.431 Miles South of FM0516 on IH0020	0.52 mile(s) before 0050	0.15 mile(s) before 0048	7/11/2024 2:42:00 PM	7/31/2025 5:00:00 PM	
Condition Descriptions			- Follow the marked detour							
Ward	Construction	SH0018	North and Southbound	881.76 Feet West of FM1219 on SH0018	63.36 Feet South of BI0020D on SH0018	0.04 mile(s) before 0344	0.39 mile(s) before 0352	11/30/2023 1:59:00 PM	12/1/2024 6:00:00 PM	
Condition Descriptions			- Delays due to slow moving road repair operations.							
Winkler	Construction	SH0302	East and Westbound	42.24 Feet West of SH0115 on SH0302	7.67 Miles West of FM1232 on SH0302	0.36 mile(s) before 0222	0.55 mile(s) after 0208	5/2/2024 2:59:00 PM	12/31/2024 5:00:00 PM	
Condition Descriptions			- Delays due to slow moving road repair operations.							